

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BULLETIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model		S/N					
		Partenavia	Partenavia P68 Observer		324-17Ob					
Item	Service Bulletins Variant Affected Effective Rev. Date	Description	Appl.	Remarks / Not apply due	Once / Recurrent	C/W	Complied	Interval	Due	WRN
1	S/B No53 P68-P68B-P68C-P68Obs Oct-81	Engine air alternate tube	INFORM.	At next Inspection	Once	Date				
						Hrs	See Aicft Book Nº 4477, SCQ from 09/01/1984			
						Cyc.				
2	S/B No53 P68-P68B-P68C-P68Obs Nov-18	REVISION OF EMERGENCY PROCEDURES ON AFM .	ALERT	N/A to A/C Config. P.68 variants equipped with Garmin G950 ICDS	N/A	Date	11-Dec-18			
						Hrs	9269	N/A	N/A	N/A
						Cyc.	4229			
3	S/B No56 P68-P68B-P68C-P68Obs Oct-82	Flap bellcrank attach. mounting brackets	MAND	As specified in SB	Once	Date				
						Hrs	See Aicft Book Nº 4477, SCQ from 09/01/1984			
						Cyc.				
4	S/B No57 P68-P68B-P68C-P68Obs Mar-83	Stab. Torque tube bracket attach. Bolts	MAND	Inmediately	Once	Date				
						Hrs	See Aicft Book Nº 4477, SCQ from 09/01/1984			
						Cyc.				
5	S/B No60 See LYC S/B Feb-94	Lycoming S/B No 466	Recom.	See LYC S/B	Once	Date				
						Hrs	Aplicado con el cambio de motor			
						Cyc.				
6	S/B No61 R3 P68-P68B-P68C-P68Obs Nov-95	Fuel and Janitrol lines	MAND	In the next 50 FH or 30 days of S/B reception	Once	Date	26-Feb-09			
						Hrs	6568	N/A	N/A	N/A
						Cyc.				
7	S/B No62 P68-P68B-P68C-P68Obs Jun-84	Rudder upper hinge bracket	INFORM.	On customer option Lyc. 301B A	Once	Date	14-Apr-87			
						Hrs	802	N/A	N/A	N/A
						Cyc.				
8	S/B No63 R1 P68-P68B-P68C-P68Obs Jun-84	Stab. Control stop	MAND	At next 100 FH Inspection	Once	Date	31-Aug-84			
						Hrs	152	N/A	N/A	N/A
						Cyc.				
9	S/B No64 R1 P68-P68B-P68C-P68Obs Sep-84	Aileron control chain	MAND	Inmediately (A/D 850806)	Once	Date	27-Jan-91			
						Hrs	1872	N/A	N/A	N/A
						Cyc.				

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BOULLETTIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model			S/N				
		Partenavia	Partenavia P68 Observer		324-17Ob					
10	S/B No65 R3 P68-P68B-P68C-P68Obs Sep-85	Spar cap cracks	MAND	Terminating Repetitive Action Installed SK 068-038 Repaired as per Mod R0090 + R0088.	Terminate	Date	29-Jun-20	N/A	N/A	N/A
						Hrs	9424			
						Cyc.				
11	S/B No68 P68-P68B-P68C-P68Obs Jan 86	Interfrence between brake oil tube nad right hand aileron cable	MAND	Within next 10 FH	Once	Date	10-Jun-86	N/A	N/A	N/A
						Hrs	606			
						Cyc.				
12	S/B No70R2 P68-P68B-P68C-P68Obs Jan 89	Engine Mount/Wing attachment bracket p/n 68-1.2025(B)-1/2; 68- 1.2027-1	MAND	Sect1: AT 5Years SN. Sect3: Every 500hr or 2Y from Sect1	Recurrent	Date	29-Jun-20	24	29-Jun-22	440
						Hrs	9424	500	9924	419
						Cyc.				
13	S/B No71 P68-P68B-P68C-P68Obs Sep-86	AVCO Lycoming S/B N° 473	MAND	Refr to LYC S/B	Once	Date	25-Apr-04	N/A	N/A	N/A
						Hrs	5881			
						Cyc.				
14	S/B No72 P68-Variants Feb_88	Rudder Controls Cable	Recom.	3500hr	Recurrent	Date	29-Jun-09	3500	10135	630
						Hrs	6635			
						Cyc.	3279			
15	S/B No73 R1 P68-P68B-P68C-P68Obs Jul-88	STB Trim Tabs	MAND	Within next 100FH Inpect (A/D 882104)	Once	Date	5-May-89	N/A	N/A	N/A
						Hrs	1401			
						Cyc.				
16	S/B No74 P68-P68B-P68C-P68Obs Nov-88	Electrical System	Recom.	Every 500FH or at least every 2Y	Recurrent	Date	28-May-19	24	28-May-21	49
						Hrs	9283	500	9783	278
						Cyc.				
17	S/B No75 R1 P68-Series Jan-89	Flight Control Cables	MAND	Every 100,FH as indicated in SB	Recurrent	Date	29-Jan-21	100	9563	58
						Hrs	9463			
						Cyc.				
18	S/B No76 R1 P68-P68B-P68C-P68Obs Jan-89	Engine Mount Installation	MAND	As specified in SB. Before further flight and after each engine dismount	Recurrent	Date	27-Jan-91	N/A x Applicac. del S/B 70R2		
						Hrs	1872			
						Cyc.				
19	S/B No77 R1 P68-P68B-P68C-P68Obs Apr-04	Cargo Version	MAND	On customer option (A/D 890303)	Once	Date	1-Mar-89	N/A	N/A	N/A
						Hrs	1361			
						Cyc.				

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BOULLETTIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model				S/N			
		Partenavia	Partenavia P68 Observer			324-17Ob				
20	S/B No79 P68-P68B-P68C-P68Obs Mar_91	Increase MTOW	INFORM.	On customer option	Once	Date		At owner's discretion		
						Hrs				
						Cyc.				
21	S/B No80 P68-P68B-P68C-P68Obs Mar_91	Large Nose wheel installation	INFORM.	On customer option	Once	Date		At owner's discretion		
						Hrs				
						Cyc.				
22	S/B No81 R1 P68-P68B-P68C-P68Obs Nov_94	Eng. & Propeller Control cables	MAND	In the next 25 FH or 30 days of S/B reception	Once	Date	24-Mar-03	N/A	N/A	N/A
						Hrs	5573			
						Cyc.				
23	S/B No83 P68-P68B-P68C-P68Obs Feb-91	Muffler assy LH and RH p/n 6.1033-3/4	MAND	At the next 100hr Insp and every 200 hr	Recurrent	Date	17-Oct-19	200	9578	73
						Hrs	9378			
						Cyc.				
24	S/B No85 Part B P68-P68B-P68C-P68Obs Jul-91	Horizontal Tail Plane	MAND	At the next 100hr Inspect.	Once	Date	29-Jul-91	N/A	N/A	N/A
						Hrs	2099			
						Cyc.				
25	S/B No86 P68-P68B-P68C-P68Obs Feb-92	Fuel and engine oil instruments system	Recom.	On customer option or in case of leakeage in proxi. of AN894D4-2 Reduction.	Recomended	Date		At owner's discretion		
						Hrs				
						Cyc.				
26	S/B No87 R1 P-68 variants Apr-92	Stab. Torque tube	MAND	Within next 50Hs from SB recept.and every 200FH as specified in SB.	Recurrent	Date	17-Oct-19	200	9578	73
						Hrs	9378			
						Cyc.				
27	S/B No88 P68-P68B-P68C-P68Obs Nov-93	Engine oil cool system hoses (NOR7.405-1)	MAND	Within next 25Hs from SB recept.and every oil cooler hose replac.200FH as specified in SB.	Recurrent	Date	25-Feb-14	8016	Each oil coler hose replacement	
						Hrs				
						Cyc.				
28	S/B No89 P68-P68B-P68C-P68Obs Nov-93	IFR Instruments panel Configuration	MAND	Within 6 months of approval date of this SB	Once	Date	1-Jun-94	N/A	N/A	N/A
						Hrs	2989			
						Cyc.				
29	S/B No90 P68-P68B-P68C-P68Obs Nov-93	Fuel Selector Control	MAND	On SB reception	Once	Date	8-Feb-94	N/A	N/A	N/A
						Hrs	2894			
						Cyc.				

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BOULLETIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model				S/N				
		Partenavia	Partenavia P68 Observer			324-17Ob					
30	S/B No91 P-68 variants Jul-91	Stab. T Tube att. Shelv. (5.3017-1/2)	MAND	At next 100H Inspection	Recurrent	Date	29-Jun-20	12	29-Jun-21	80	
		Hrs				9424	200	9624	119		
		Cyc.									
31	S/B No93 P-68 variants Nov-95	Inspection of the internal area of the wing box betw. Ribs N°6 and 8 (Eng. Nacellearea)	MAND	a) >500=500; 500=Next100 b) 300 or 500(Rep Insp) c) 2000H after replac.	Recurrent	Date	22-Aug-17				
		Hrs				9124	500	9624	119		
		Cyc.									
32	S/B No95R2 P-68 variants May-11	Supersede S/B 75 si cambias a cable Carbono.	Recom.	No se han cambiado la totalidad de cables x lo que se cumple el S/B 75 cada 100hs	ONCE	Date					
		Hrs				N/A	N/A	N/A	N/A		
		Cyc.									
33	S/B No97R1 P-68 variants May-49	ADDITIONAL STATIC WICKS INSTALLATION	Recom.	N/A por A/C S/N	ONCE	Date					
		Hrs				N/A	N/A	N/A	N/A		
		Cyc.									
34	S/B No98 P68-P68B-P68C-P68Obs Jul-99	NLG Inspection / Replacement	MAND	Within next 200FH fro orwithin 12M of the approval date of S/B wichever first occurs	Once	Date	18-Aug-01				
		Hrs				5027	N/A	N/A	N/A		
		Cyc.									
35	S/B No99 R1 P-68 variants Mar-00	LH & RH Bolts att. The MLG leaf spring joints to the fuselahje centre bean	MAND	On SB reception	Once	Date	7-Aug-00				
		Hrs				4690	N/A	N/A	N/A		
		Cyc.									
36	S/I No61 R1 P-68 variants Jun-00	New EGT Indicator System Indic. NOR7.1035-1C (Alcor P/N 46198) Probe NOR7.323-18B (Alcor P/N 86255)	MAND	New EGT Indicator replacing original syst. Replaced original indicator Skit SI61	Once	Date	7-Aug-00				
		Hrs				4690	N/A	N/A	N/A		
		Cyc.									
37	S/B No101 P-68 Obs Feb-19	INSTALLATION OF SEAT TRAVEL STOP AFT TO THE LH 2nd ROW PASSENGER SEAT	Owner	N/A por A/C S/N	Once	Date		At owner's discretion			
		Hrs									
		Cyc.									
38	S/B No102 P-68 Obs Apr-19	PROVISIONS FOR ANTENNAS INSTALLATION	INFORM.	N/A por A/C S/N	Once	Date					
		Hrs				N/A	N/A	N/A	N/A		
		Cyc.									
39	S/B No107 P-68C -P68Obs2 May-18	INSTALLATION OF NEW DE-ICE BOOT AIR FILTER P/N NV7.003-236A (RAPCO P/N RA2J4-7)	MAND	N/A por A/C S/N	Once	Date					
		Hrs				N/A	N/A	N/A	N/A		
		Cyc.									

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BOULLETTIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model		S/N					
		Partenavia	Partenavia P68 Observer	324-17Ob						
40	S/B No110 P68-P68B-P68C-P68Obs Mar-02	F. Ctrl-Insp. To ensure abs. interf. Btwn ctrl column intercon.	MAND	Part A: before next flight at SB recept. Part B: Within 30 day after SB recept.	Once	Date	12-Feb-03	N/A	N/A	N/A
						Hrs	5526			
						Cyc.				
41	S/B No111 R1 P-68 variants Jul-91	Aileron Cntrl								

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BOULLETIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model			S/N				
		Partenavia	Partenavia P68 Observer			324-17Ob				
50	S/B No134 P-68 variants Jul-08	Fuel Tank reconfiguration from "STD Range" to "Long Range"	INFORM.	At owners discretion	Information	Date		At owner's discretion		
						Hrs				
						Cyc.				
51	S/B No141 P-68 variants Aug-91	Retrofit of the "Keith" Air condition system	INFORM.	At owners discretion	Information	Date		At owner's discretion		
						Hrs				
						Cyc.				
52	S/B No143 P68-P68B-P68C-P68Obs Sep-06	Installation of new windshield	INFORM.	At owners discretion	Information	Date		At owner's discretion		
						Hrs				
						Cyc.				
53	S/B No144 P-68 variants Oct-06	Instal. of travel stop at full pos. of the fuel level Transm. Farem p/n NOR7.289-1LH & NOR7.289-1A RH	INFORM.	At owners discretion	Information	Date		At owner's discretion		
						Hrs				
						Cyc.				
54	S/B No162 P-68 variants Mar-10	Wing Safe Limit Special Insp on wing structures iaw Table 2-2, paragraph 3.1 AMM Supp NOR10,771-52	MAND	As indicated in Table 2-2, paragraph 3.1 AMM Supp NOR10,771-52	Once	Date	8-Sep-10 7156	6000	12000	2494,90
						Hrs				
						Cyc.				
55	S/B No162 R1 P-68 variants Mar-10	Special Insp Stabilator structures iaw Table 2-3, paragraph 3.2 AMM Supp NOR10,771-52	MAND	As indicated in Table 2-3, paragraph 3.2 AMM Supp NOR10,771-532	Once	Date	28-May-19 9283	500	9783	277,90
						Hrs				
						Cyc.				
56	S/B No163 Rev 17 P-68 variants Jan-19	Mechanical Interface for install. of an aparatus on the photog. Hatch	INFORM.	At owners discretion	Information	Date		At owner's discretion		
						Hrs				
						Cyc.				
57	S/B No164 Rev0 P-68 variants Feb-17	RFI FILTER REPLACEMENT	INFORM.	At owners discretion	Information	Date		At owner's discretion		
						Hrs				
						Cyc.				
58	S/B No174 Rev0 P-68 variants Apr-19	REPLACEMENT OF SAGEM ICDS-8 DISPLAY	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
59	S/B No178 P-68 variants Mar-13	Installation Low Press. Fuel Filter STEVE'S Aircraft P/N SA3-00-BS (Vulcanair P/N NV7.003-45)	Optional	To inform for installing the new fuel filter p/n NV7.003-45. Installed Service Kit 178A	Once		29-Jul-13 7881 3720	N/A	N/A	N/A
60	S/B No180 P-68 variants Mar-09	Inst. Of Artex Model ME406 ELT as per change No Mod.P68/77	INFORM.	At owners discretion	Information	Date		At owner's discretion		
						Hrs				
						Cyc.				

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BOULLETTIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model			S/N					
		Partenavia	Partenavia P68 Observer			324-17Ob					
60	S/B No183R17 P-68 variants Feb-18	REPLAC. OF THE SAFETY BELTS P/N NOR7.229-1 (INERTIAL) & NOR7.229-2 (VENTRAL) WITH NEW P/N	INFORM.	At owners discretion	Information	Date	28-Jun-13	N/A	N/A	N/A	
						Hrs	7863				
						Cyc.					
61	S/B No192 P-68 variants Nov-09	INTERFERENCE BTWN NEW TO-360-C1A6D ENGINE CRANKCASE	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A	
						Hrs					
						Cyc.					
62	S/B No195R1 P-68 variants Mar-14	REPLACE HALOGEN NAV AND STROBE LIGHTS WITH NEW LED LIGHTS	INFORM.	At owners discretion	Information	Date		At owner's discretion			
						Hrs					
						Cyc.					
63	S/B No198 P-68 Apr-19	REDUC MTOW FROM 2063 TO 1960 Kg & INCREMENT MTOW FROM 1960 TO 2063 Kg	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A	
						Hrs					
						Cyc.					
64	S/B No199 P-68 variants Nov-09	Fire Exting. P/NosNOR7.227-5aAand NOR7,227-5B manuf. by Fire Fighting Enterp. Limited with P/N BA51015-3 and B51015G-3--Identif. replacemnt.	MAND	WITHIN 29 JANUARY 2010 Fire Ext. Installed not affected	N/A	Date	25-Nov-09	N/A	N/A	N/A	
						Hrs	2595				
						Cyc.					
65	S/B No200 P-68 variants Jun-10	Installation of safety guard for right lower aileron pulley located on fuselaje frame n°8	Recom.	Within next 100Hrs inspect. or 1 year.	Once	Date	N/A	N/A	N/A	N/A	
						Hrs					
						Cyc.					
66	S/B No201R1 P-68 variants Apr-13	ALTERNATIVE SEATS INSTALLATION	Recom.	Within next 100Hrs inspect. or 1 year.	Information	Date		At owner's discretion			
						Hrs					
						Cyc.					
67	S/B No202R1 P-68 variants Feb-11	FLIGHT CONTROL TURNBUCKLES INSPECTION/REPLACEMENT	Recom.	Within next 100 Hrs inspect. or 1 year.	Recommended	Date		At owner's discretion			
						Hrs					
						Cyc.					
68	S/B No203 P-68 variants Oct-10	AIRCRAFT FLIGHT MANUAL CHANGE	MAND	N/A por A/C S/N	N/A	Date	N/A	N/A	N/A	N/A	
						Hrs					
						Cyc.					
69	S/B No204 P-68 R Jul-10	INSTL. OF IMPROVED LANDING GEAR HYDRAULIC ACTUATOR	INFORM.	N/A por A/C S/N	N/A	Date	N/A	N/A	N/A	N/A	
						Hrs					
						Cyc.					
70	S/B No205 P-68 R Nov-10	STRUCTURAL IMPROVEMENT BETWEEN THE FUSELAGE FRAMES No. 8 AND 9	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A	
						Hrs					
						Cyc.					

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BOULLETTIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model			S/N				
		Partenavia	Partenavia P68 Observer	324-17Ob						
71	S/B No206 P-68 R Nov-10	LG HYDRAULIC PUMP ANNUNCIATION LIGHT SYSTEM INSTALLATION	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
72	S/B No207 P-68 variants Dec-11	DRAIN HOLES ON STABILATOR	INFORM.	Achievement of drain holes on stab ventral skins (LH and RH) and on circular inspection hatches.	Information	Date	At owner's discretion			
						Hrs				
						Cyc.				
73	S/B No208 P-68 variants Dec-11	INSTALLATION OF NEW IMPROVED FAN HEATER	INFORM.	Heater P/N 1305290 can be replaced by Vulcanair P/N 7.6221-402 and 402	Information	Date	At owner's discretion			
						Hrs				
						Cyc.				
74	S/B No209 P-68 R Dec-11	LG HYDRAULIC PUMP ADDITIONAL "PUMP ON" ANNUNCIATION AMBER LIGHT	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
75	S/B No210 P-68 variants Jan-11	NEW BATTERY CONCORDE RG24-20 (VULCANAIR P/N NV7.003-96)	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
76	S/B No212 R2 P-68 variants May-11	CHANGE IN FUEL PRESSURE TRANSDUCER INSTALLATION	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
77	S/B No213 P-68 R Jan-11	NEW ADDITIONAL DUST BOOT ON NLG STEERING ROD	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
78	S/B No214 P-68 variants Feb-11	AIRCRAFT FLEET DATA	MAND	Actualizar datos de aeronaves en base datos de Vulcanair	Once	Date	31-Mar-11 7359 3545	N/A	N/A	N/A
						Hrs				
						Cyc.				
79	S/B No215 P-68 variants Mar-11	HONEYWELL (EX BENDIX/KING) KFC- 150 FLIGHT CONTROL SYSTEM	Recom.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
80	S/B No216 P-68 TC Feb-11	28 Vdc, 30 Amp. MAX AUXILIARY POWER SOCKET INSTALLATION	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
81	S/B No218R1 P-68 R Sep-11	INSTLL. NEW IMPROVED LG HYD. ACTUATORS AND MLG DOWN LOCKING MECH.	Recom.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
82	S/B No219 P-68 variants Jul-10	INSTALLATION OF SEATS WITH NEW INTERMEDIATE BACKREST RECLINE POSITION	INFORM.	N/A	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BOULLETIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model			S/N				
		Partenavia	Partenavia P68 Observer		324-17Ob					
83	S/B No220R2 P-68 variants Dec-16	REPLCMNT LORD AEROSPACE ENGINE VIBRATION ISOLATORS WITH BARRY CONTROLS AEROSPACE ONES	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
84	S/B No221 R13 P-68 variants Mar-20	INSTALLATION OF BUBBLE WINDOWS	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
85	S/B No222R1 P-68 variants Jun-17	CABIN AIR HEATING SYSTEM RECONFIGURATION	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
86	S/B No223R2 P-68 variants Jun-14	28 Vdc, 30 Amp. MAX AUXILIARY POWER SOCKET INSTALLATION	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
87	S/B No225 R1 P-68 variants Mar-13	AERIAL SURVEY CONFIGURATION - WESCAM MX-15i AIRBORNE IMAGING SYSTEM INSTALLATION	INFORM.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
88	S/B No226 P-68 variants Nov-12	New flage frame No.16 P/N 2.5015-003 now available in replac. of P/N 2.5015- 1 no longer available.	INFORM.	All P.68 aircraft variants up to s/n 468, except s/n 463. Kit SB226	Information	Date	At owner's discretion			
						Hrs				
						Cyc.				
89	S/B No227 P-68 variants Jan-12	REPLACEMENT OF LG HYDRAULIC POWER UNIT P/N HYH5001 WITH NEW ONE P/N NV7.003.140A	INFORM.	P.68R S/N 453 and 457. ,Replac. of LG Hyd. Pwr Unit P/N HYH5001, no longer avail., with P/N NV7.003-140A..	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
90	S/B No228R2 P-68 variants Jun-12	IMPROVEMENT IN THE EXISTING ELECTRICAL CUT-OFF SYSTEM	INFORM.	P.68C s/n 437 and 469.	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
91	S/B No229 P-68 variants May-12	REPLAC. OF "MT-PROP" THREE- BLADES PROP WITH "HARTZELL" TWO-BLADES ONES	INFORM.	P68 Obs # 423 ; P68C; P68C-TC, P68 Obs 2 & P68TC Obs from # 442 and on equipped with "MT-PROP"	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
92	S/B No230 P-68 variants Jun-12	BOX IN THIRD SEAT ROW	INFORM.	P.68C, P.68C-TC, P.68 Obs 2 and P.68TC Obs from S/N 413 onwards	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
93	S/B No231 P-68 variants Oct-12	REPLACEMENT OF CASTING FIN TO FUSELAGE ATTACHMENTS WITH NEW MACHINED ONES	INFORM.	Inform new fin to fus. attach, front P/N 3.2009-003 and rear P/N 3.2011-003 ...	Information P.68B S/N 64,	Date	At owner's discretion			
						Hrs				
						Cyc.				
94	S/B No232R1 P-68 variants Apr-13	ACTIVAT. OF ALT. PRESELECT FUNCT. ON GARMIN G950 INTEGRATED COCKPIT SYST.	INFORM.	P.68C s/n 471 P.68 Observer 2 s/n 466 and 473	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BOULLETTIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model			S/N				
		Partenavia	Partenavia P68 Observer	324-17Ob						
95	S/B No233R2 P-68 variants Jun-14	ACTIVAT. OF ALT. PRESELECT FUNCT. ON GARMIN G950 INTEGRATED COCKPIT SYST.	INFORM.	Only for s/n 458 and 465 the G950 sofware. Must be updated	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
96	S/B No234R2 P-68 variants Aug-19	REPLAC.OF HEATED STALL DETECTOR P/N NOR7.387-1 WITH NEW ONE P/N 7.7600-401	INFORM.	All P.68 aircraft variants, if they install the heated stall detector p/n NOR7.387-1.	Information	Date	At owner's discretion			
						Hrs				
						Cyc.				
97	S/B No235R2 P-68 variants May-19	ACTIVATION OF FUEL CALC. FEATURE ON GARMIN G950 INTEGRATED COCKPIT SYSTEM	INFORM.	P.68 aircraft s/n 458, 463, 465, 466, 469, 470, 471, 473 and 474.	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
98	S/B No236R1 P-68 variants May-14	TRIPLE ENGINE INDICATOR (OIL TEMP / OIL PRES / CHT) VERIFICATION	MAND	A/C Inspected. No discrepancies were detected	Once	Date	23-Jun-14 8160	N/A	N/A	N/A
						Hrs				
						Cyc.				
99	S/B No237 P-68 variants Oct-13	SLIDING WINDOWS INSTALLATION	INFORM.	P.68 Observer 2 S/N 465.	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
100	S/B No239 P-68 variants Jan-14	STRUCTURAL IMPROVEMENT OF MLG ATTACHMENTS	Recom.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
101	S/B No240R3 P-68 variants Mar-18	REPLACEMENT OF HALOGEN TAXI AND LANDING LIGHTS WITH NEW LED LIGHTS	Recom.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
102	S/B No241 P-68 variants Nov-14	INSTALLATION OF MECHANICAL FLAP TRAVEL STOP AT FLAPS UP POSITION	Recom.	P68 VARIANTS	Recommended	Date	At owner's discretion			
						Hrs				
						Cyc.				
103	S/B No242R1 P-68 variants Dec-16	IMPROVEMENT OF PHOTOGRAMMETRIC HATCH	Info.	N/A por A/C MODEL	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
104	S/B No243 P-68 variants Apr-15	REPLAC. OF LG HYD. SYST. TWIN SHUT-OFF VALVES P/N 72CA0033 WITH NEW ONES P/N	Recom.	N/A por A/C MODEL	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
105	S/B No244 P-68 variants Apr-15	AIRCRAFT FLIGHT MANUAL CHANGE	MAND	N/A por A/C MODEL	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
106	S/B No245 R2 P-68 variants May-19	ELECTRICAL IMPROVEMENT OF 2nd PITOT TUBE	Recom.	N/A por A/C MODEL and S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BOULLETTIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model			S/N				
		Partenavia	Partenavia P68 Observer		324-17Ob					
107	S/B No246 P-68 variants Jun-15	INSTALLATION OF FWD SEAT TRAVEL STOP ON THE PILOT AND CO-PILOT SEAT TRACKS	Recom.	N/A por A/C MODEL	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
108	S/B No247 P-68 variants Feb-16	PROCEDURE FOR AIRCRAFT DISASSEMBLING, SHIPPING, RE-ASSEMBLING AND TESTING INST. NEW FUEL LEVEL INDIC.	Recom.	RESERVED	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
109	S/B No248 P-68 variants Oct-15	SYST.	Recom.	N/A por A/C MODEL	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
110	S/B No249 P-68 variants May-16	REPLACEMENT OF STABILATOR TORQUE TUBE SUPPORTS P/N 5.3017-1/-2	Recom.	P.68 Variants up to s/n 481	Information	Date	At owner's discretion			
						Hrs				
						Cyc.				
111	S/B No250 P-68 variants Nov-17	RELOCATION OF MAGNETOMETER GMU 44	Recom.	N/A por A/C Model and S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
112	S/B No251 P-68 variants Nov-17	AIRCRAFT FLIGHT MANUAL CHANGE	Recom.	N/A por A/C S/N	Mandatory	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
113	S/B No252 P-68 variants Nov-17	NEW GARMIN LOADER CARD TO UPDATE G950 SOFTWARE	Recom.	N/A por A/C S/N	Recommended	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
114	S/B No253 P-68 variants Jan-18	INSTALLATION OF PILOT AND CO-PILOT SEATS WITH REDUCED BACKREST RECLINE POSITION	Recom.	N/A por A/C S/N S/N 503 Only	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
115	S/B No254 P-68 variants May-18	REPLACEMENT OF FUEL SELECTOR VALVE	Recom.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
116	S/B No255 P-68 variants Feb-18	IMPROVEMENT OF L/G NITROGEN LINE FOR EXTERNAL CHARGING	Recom.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
117	S/B No256 P-68 variants Sep-18	REPLAC. OF ATTITUDE GYRO PLACARD (if installing the Stand-by ADI instrument p/n NV7.003-89A)	Recom.	P68 Variants	Information	Date	At owner's discretion			
						Hrs				
						Cyc.				
118	S/B No257 P-68 variants Jun-18	CO PREVENTION IMPROVEMENTS	Recom.	P.68 variants up to s/n 474, except s/n 472	Information	Date	At owner's discretion			
						Hrs				
						Cyc.				

A/C	EC-DTS
Date	9-Apr-21
A/C TTF	9505,10
A/C Cycles	4373

SERVICE BOULLETTIN COMPLIANCE RECORD

AIRFRAME		Manufact.:	Model			S/N				
		Partenavia	Partenavia P68 Observer			324-17Ob				
119	S/B No258 P-68 variants Jan-19	IMPROVEMENTS TO THE ELECTRICAL SYSTEM	RESERVED.	P.68 variants up to s/n 499, except s/n 507	Information	Date	At owner's discretion			
						Hrs				
						Cyc.				
120	S/B No259 P-68 variants Jan-19	SVS FEATURE ENABLEMENT Supply information to upload the Garmin G9502	Recom.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
121	S/B No260 P-68 variants Oct-19	E-CONFIGURATION OF THE ELECTRICAL CIRCUIT OF CABIN AIR HEATING SYSTEM	Recom.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				
122	S/B No261 P-68 variants Nov-19	NEW GARMIN LOADER CARD TO UPDATE G950 SOFTWARE	Recom.	N/A por A/C S/N	Information	Date	N/A	N/A	N/A	N/A
						Hrs				
						Cyc.				