

ANNEX III.- ESTOC MÍNIM INICIAL DEL DIPÒSIT LOGÍSTIC

DIPÒSIT LOGÍSTIC	DESCRIPCIÓ MATERIAL	TIPO DE MATERIAL: SEGURETAT (MS) HABITUAL (MH)	UNITAT DE MESURA	Estoc Mínim
CERVERA	Tubería de Fundición PN 16 DN 200	MS	M	4
CERVERA	Tubería de Fundición PN 16 DN 250	MS	M	4
CERVERA	BRIDA LOCA AC ZINCAD.PE 180 DN150 PN16	MH	UD	2
CERVERA	BRIDA LOCA AC ZINCAD.PE 200 DN200 PN16	MH	UD	2
CERVERA	TUB PE100 AD SDR11 DN 50 PN16 B6	MS	M	8
CERVERA	TUB PE100 AD SDR11 DN 63 PN16 B6	MS	M	8
CERVERA	TUB PE100 AD SDR11 DN 75 PN16 B6	MS	M	8
CERVERA	TUB PE100 AD SDR11 DN 90 PN16 B6	MS	M	8
CERVERA	TUB PE100 AD SDR11 DN 110 PN16 B6	MS	M	8
CERVERA	TUB PE100 AD SDR11 DN 140 PN16 B6	MS	M	8
CERVERA	TUB PE100 AD SDR11 DN 160 PN16 B16	MS	M	4
CERVERA	TUB PE100 AD SDR11 DN 200 PN16 B6	MS	M	4
CERVERA	UNION UNIV.3007+STOP-UNI/F.200(192-232)	MS	UD	2
CERVERA	UNION UNIVERSAL 175 (193-215) PN16 S-601	MS	UD	2
CERVERA	MANGUITO ELECTROS.PE100 SDR11 DN 50 PN16	MH	UD	2
CERVERA	MANGUITO ELECTROS.PE100 SDR11 DN 63 PN16	MH	UD	4
CERVERA	MANGUITO ELECTROS.PE100 SDR11 DN 75 PN16	MH	UD	4
CERVERA	MANGUITO ELECTROS.PE100 SDR11 DN 90 PN16	MH	UD	4
CERVERA	MANGUITO ELECTROS.PE100 SDR11 DN110 PN16	MH	UD	4
CERVERA	MANGUITO ELECTROS.PE100 SDR11 DN125 PN16	MH	UD	4
CERVERA	MANGUITO ELECTROS.PE100 SDR11 DN140 PN16	MH	UD	4
CERVERA	MANGUITO ELECTROS.PE100 SDR11 DN160 PN16	MH	UD	2
CERVERA	MANGUITO ELECTROS.PE100 SDR11 DN180 PN16	MH	UD	2
CERVERA	MANGUITO ELECTROS.PE100 SDR11 DN200 PN16	MH	UD	4
CERVERA	COLZE 90º ELECTROS.PE100 SDR11 DN63 PN16	MH	UD	2
CERVERA	COLZE 90º ELECTROS.PE100 SDR11 DN75 PN16	MH	UD	2
CERVERA	COLZE 90º ELECTROS.PE100 SDR11 DN90 PN16	MH	UD	2
CERVERA	COLZE 90º ELECTROS.PE100 SDR11 DN110 PN16	MH	UD	2

CERVERA	COLZE 90º ELECTROS.PE100 SDR11 DN125 PN16	MH	UD	2
CERVERA	COLZE 90º ELECTROS.PE100 SDR11 DN160 PN16	MH	UD	2
CERVERA	BRIDA LOCA AC ZINCAD.PE 63 DN 50 PN16	MH	UD	2
CERVERA	BRIDA LOCA AC ZINCAD.PE 75 DN 65 PN16	MH	UD	2
CERVERA	BRIDA LOCA AC ZINCAD.PE 140 DN125 PN16	MH	UD	2
CERVERA	UNION UNIV.3007+STOP-UNI/F. 80(84-105)	MS	UD	2
CERVERA	UNION UNIV.3007+STOP-UNI/F.100(104-132)	MS	UD	2
CERVERA	UNION UNIV.3007+STOP-UNI/F.150(154-192)	MS	UD	2
CERVERA	MANG.SOL.TOPE BRIDA PE100 SDR11 63 PN16	MH	UD	2
CERVERA	MANG.SOL.TOPE BRIDA PE100 SDR11 75 PN16	MH	UD	2
CERVERA	MANG.SOL.TOPE BRIDA PE100 SDR11 90 PN16	MH	UD	2
CERVERA	MANG.SOL.TOPE BRIDA PE100 SDR11 110 PN16	MH	UD	2
CERVERA	MANG.SOL.TOPE BRIDA PE100 SDR11 125 PN16	MH	UD	2
CERVERA	MANG.SOL.TOPE BRIDA PE100 SDR11 140 PN16	MH	UD	2
CERVERA	MANG.SOL.TOPE BRIDA PE100 SDR11 160 PN16	MH	UD	2
CERVERA	MANG.SOL.TOPE BRIDA PE100 SDR11 180 PN16	MH	UD	2
CERVERA	MANG.SOL.TOPE BRIDA PE100 SDR11 200 PN16	MH	UD	2
CERVERA	BRIDA LOCA AC ZINCAD.PE 90 DN 80 PN16	MH	UD	2
CERVERA	BRIDA LOCA AC ZINCAD.PE 160 DN150 PN16	MH	UD	2
CERVERA	CODO 45º ELECTROS.PE100 SDR11 DN63 PN16	MH	UD	2
CERVERA	CODO 45º ELECTROS.PE100 SDR11 DN75 PN16	MH	UD	2
CERVERA	CODO 45º ELECTROS.PE100 SDR11 DN90 PN16	MH	UD	2
CERVERA	CODO 45º ELECTROS.PE100 SDR11 DN110 PN16	MH	UD	2
CERVERA	CODO 45º ELECTROS.PE100 SDR11 DN125 PN16	MH	UD	2
CERVERA	CODO 45º ELECTROS.PE100 SDR11 DN160 PN16	MH	UD	2
CERVERA	UNION UNIVERSAL 150 (157-183) PN16 S-601	MS	UD	2
CERVERA	UNION UNIVERSAL 175 (193-215) PN16 S-601	MS	UD	2
CERVERA	UNIO UNIVERSAL 200 (218-242) PN16 S-601	MS	UD	2
CERVERA	UNIO UNIVERSAL 225 (242-268) PN16 S-601	MS	UD	2
CERVERA	UNIO UNIVERSAL 250 (266-292) PN16 S-601	MS	UD	2

CERVERA	UNIO UNIVERSAL 300 (324-350) PN16 S-601	MS	UD	2
CERVERA	UNIO UNIVERSAL 350 (372-396) PN16 S-601	MS	UD	2
CERVERA	BRIDA LOCA AC ZINCAD.PE 110 DN100 PN16	MH	UD	2
CERVERA	UNION UNIV.3007+STOP-UNI/F.125(132-155)	MS	UD	2
CERVERA	BRIDA LOCA AC ZINCAD.PE 125 DN100 PN16	MH	UD	2